

What Lies Beneath

Healthcare Estates

7th October 2014

Envirosafe UK Ltd

Content

- ❑ Introduction to the speaker
- ❑ GRP tanks
- ❑ Sterilisation techniques
- ❑ Pseudomonas Aeruginosa in new systems
- ❑ Questions

David Tamblyn

- BSC Hons. Degree in Chemistry & Management**
- 5 Years as a Chemical Water Treatment Rep – esp. Steam Boilers in Hospitals.**
- 6 Years predominantly Commercial Water Treatment**
 - Legionella Compliance**
- 3 Years - Commercial & Industrial Water Treatment**
- 8 Years MD & Consultant for EnviroSAFE UK Ltd – Water Risk Assessments and Consultancy.**

Why GRP Tanks?



Envirosafe UK Ltd

Why GRP Tanks?




Envirosafe UK Ltd

Why GRP Tanks?



Before

After



Envirosafe UK Ltd



Why GRP Tanks?



Mould growing in poorly mixed paint

Envirosafe UK Ltd

Types of GRP Tanks



Hot Pressed
Sectional



Hand laid-up
one piece

Envirosafe UK Ltd



Problems with GRP Tanks



Early examples bled
sealant and could
leak

Envirosafe UK Ltd



Resulted in
recoating with
flexible paint



Problems with GRP Tanks



Mild Steel Bolts – causing
most of the debris in the tank!



Half plastic coated bolts –
where's the logic?

Envirosafe UK Ltd



Problems with GRP Tanks



Concealed Structures
DH EFA/2013/004
HSG274 Part 2 Fig 2.12 Moderate
Risk



Replacement with
Stainless Steel Supports
Photo By expresswatertanks.co.uk

Envirosafe UK Ltd

Problems with GRP Tanks

Gel Coat Failure – HSG274 P2. Fig 2.12 High Risk



Tank installed in
2013




Gel coat failure in 2013
on side hatch only

Envirosafe UK Ltd

Problems with GRP Tanks

Gel Coat Failure



One Section is fine, the adjacent one is covered in cysts

Envirosafe UK Ltd

Problems with GRP Tanks

Gel Coat Failure



One piece tank – corners often fail due to either inconsistent brush application of gel coat resin or insufficient pressure when rolling out the air between layers of fibreglass.




Bubbled/blistered surface is the first signs of osmosis

Envirosafe UK Ltd

Gel Coat Failure

One mechanism of failure



Envirosafe UK Ltd

Gel Coat Failure


Why should we care?



Envirosafe UK Ltd


Gel Coat Failure

Why should we care?



Envirosafe UK Ltd

Nematodes & biofilm



Envirosafe UK Ltd

Tank Cleaning

- ❑ Naturally, when faced with worms swimming around in your cold water storage tank, the first response is to clean the tank.
- ❑ Unfortunately we found that the cysts (and worms) were visibly back within 2 weeks.
- ❑ Chlorination tried at double the recommended concentration of chlorine for double the time (>100mg/l free chlorine for 2 hours) – cysts removed from the tank surface prior to chlorination.
- ❑ Nematode within the biofilm still alive up to 36 hours in 100mg/l chlorine!

BS8558:2011 / HSG 284 Part 2 2014

Chlorination

❑ BS8558:2011 Table 13

Initial free chlorine concentration mg/L	Contact period h:min	Minimum residual free chlorine measured at the end of the contact period mg/L
3.1	16:00	1.9
5	10:00	3
10	05:00	6
15	03:20	9
20	02:30	12
25	02:00	15
30	01:40	18
40	01:15	24
50	01:00	30

BS8558:2011 / HSG 284 Part 2 2014

Chlorination

- ❑ The chlorine contact time table was derived from testing the effectiveness of chlorine of free floating bacteria in a laboratory environment.
- ❑ Hundreds of papers have been written, high-lighting the poor performance of chlorine against biofilms.
- ❑ The water treatment industry has spent the past 20+ years advocating alternatives to chlorine due to its short comings.
- ❑ Bromine, ammonium bromide, chlorine dioxide & hydrogen peroxide have all been used to replace chlorine (only the latter 2 in drinking/potable water).

Low-tech biocide comparison study

	Time taken until dead Nematode worms are first noted	Time taken until all Nematode worms are dead
Sodium Hypochlorite @100mg/l	28 Hours	78 Hours +
Bromine (from BCDMH) @100mg/l as Cl	3 Hours	20 Hours
Ashland Generox 100 stabilised ClO ₂ @100mg/l as Cl	3 hours	20 Hours
B&V Abulox Hypochlorous acid solution @100mg/l	20 Hours	78 Hours
Aquatreat Peroxysil 50 Stabilised hydrogen peroxide solution @200mg/l	1 Hour	8 Hours
Huwa San TR50 Stabilised hydrogen peroxide solution 100mg/l	1 Hour	78 Hours

Envirosafe UK Ltd

Tank Cleaning - Field Trial

- ❑ Peroxysil 50 on 4 tanks at 1000mg/l for 16 hours.**
- ❑ The tanks were cleaned (cysts were removed) prior to chlorination to expose the GRP surface to the biocide.**
- ❑ This strength of biocide is advocated for cooling towers where biofilms are often present.**
- ❑ One tank was poorly balanced and cysts regrew within a month (tank water was at 25°C)**
- ❑ Remaining 3 tanks are much improved but not 100% clear after 1 year.**

Tank recoating



Before



After £4000!
Better but not 100%

Envirosafe UK Ltd

Supplementary Dosing

- ❑ Chlorine Dioxide is widely used in hospitals to support the water hygiene regime, especially as down service chlorinations are often impractical.**
- ❑ The results seen so far are variable. Where a good (possibly above potable level) reserve is maintained the cysts are controlled. Where ClO₂ reserves are borderline cysts may reform after cleaning.**

Pseudomonas Aeruginosa & new installation disinfection

- ❑ Back in 2009 we started working with Homerton Hospital & the HPA following the refurbishment of their SCBU ward.**
- ❑ The plumbing contractor had failed to carryout an adequate chlorination of the pipework and a biofilm had been allowed to become established.**
- ❑ Working with the HPA we agreed on what levels of pseudomonas aeruginosa were deemed to be acceptable – these levels were then adopted by the HPA and have since become HTM04 addendum.**

Pseudomonas Aeruginosa & new installation disinfection

- ❑ **Chlorination No1 - >80mg/l chlorine for 1 hour**
 - Results were poor after 5 days.
- ❑ **Chlorination No2 - >80mg/l chlorine for 1 hour, all plastic filters removed from Markwik IR taps and boiled.**
 - Results deteriorated after 2 weeks (still working on <80cfu PA per ml being acceptable)
- ❑ **Chlorination No3 - >80mg/l chlorine for 2 hours, outlets bagged and soaked for >1 hour**
 - French Limits adopted – pseudomonas levels still too high on cold services

Pseudomonas Aeruginosa & new installation disinfection



Envirosafe UK Ltd



Pseudomonas Aeruginosa & new installation disinfection

- ❑ Markwik auto flushing stopped due to Nurses complaints**
- ❑ Flushing points installed behind IPS panels.**
- ❑ UV taps proposed to Steri-spray at Combating Legionella conference 2011**
- ❑ New UV- taps developed & tested**
- ❑ Belfast SCBU hits the news**
- ❑ First batch of UV-taps diverted to Belfast by DH.**

Pseudomonas Aeruginosa & new installation disinfection

- ☐ **TMV taps removed from the SCBU on site and replaced with old-fashioned mixers.**
 - Results improved, but still not <1cfu/100ml
- ☐ **Chlorination No4 –Hot water cross linked to cold for the whole ward. >100mg/l chlorine for 2 hours @60°C plus supplementary ClO₂ dosing fixed.**
- ☐ **Results all clear.**
- ☐ **New standard adopted for all refurbishments on site. Where possible all services are chlorinated at high temperatures.**

Pseudomonas Aeruginosa & new installation disinfection - Conclusions

- ❑ Chlorine on its own cannot penetrate Pseudomonas Aeruginosa biofilms within a practical time frame.**
- ❑ The combination of thermal disinfection and chlorine helps remove grease & oils from new pipework that chlorine alone cannot.**
- ❑ The combination of thermal disinfection and chlorine is very effective at removing biofilms.**

❑ Any Questions?

Envirosafe UK Ltd
